

| PARTS LIST* | | |
|-------------|---------------|------|
| Part | Item Name | Qty. |
| Α | Table Top | 1 |
| В | Base Cabinet | 2 |
| С | Wheels | 1 |
| D | Polish Rack | 1 |
| E | Wrist Rest | 1 |
| F | Headless Bolt | 2 |
| G | Wingnuts | 2 |



Tools: Phillips-head screwdriver may be needed for drawer/door knobs and a wrench may be needed for bolts.

Remove and unwrap all pieces from shipping box. Make sure that the box(es) contain all of the listed parts before beginning assembly.

2 Table top Attatchment

- 1) Remove top drawers to access placement for bolts.
- 2) Line table top (A) up with the base cabinets (B) and screw headless bolts into the holes as shown.
- 3) Next, place wingnut over head of bolt, then turn to tighten and secure.



